

## **Table of Contents**

2

Fiat->Bianchina->Body Panels
Terms and Conditions

Page 1



### Bianchina->Body Panels



500 Internal Front Panel

BP-500-006

Internal front panel for all Fiat 500 and Bianchina models.





#### Bianchina Left Inner Rocker Panel

BP-500-019

Left inner rocker panel for Bianchina models. Part #: BP-500-019





# Bianchina Right Inner Rocker Panel

BP-500-020

Right inner rocker panel for Bianchina models. Part #: BP-500-020

\$245



#### 500 Left Floor Pan

BP-500-035

Driver's side floor pan for all Fiat 500 models and the early Fiat Autobianchina models.

\$205



#### 500 Right Floor Pan

BP-500-036

Passenger's side floor pan for all Fiat 500 models

\$205



## 500 Nuova Left Flat Floor Pan

BP-500-037

Left flat floor pan for early Fiat 500 Nuova models and Bianchina Transformable models.

\$356



## 500 Nuova Right Flat Floor Pan

BP-500-038

Right flat floor pan for early Fiat 500 Nuova models and Bianchina Transformable models.

\$370



### 500 R Internal Dashboard Panel

BP-500-107

Internal dashboard panel for Fiat 500 R and Autobianchi Giardina models.

\$360



#### **Bianchina Front Panel**

BP-A500-001

Front panel Bianchina models.



#### Bianchina Transformabile Front... BP-A500-002

Front panel for the all Bianchina Transformabile models from 1957-59.

\$895



#### **Bianchina Fender Left**

BP-A500-003

Left fender for all Bianchina models from 1957-1960.

\$595



#### Bianchina Fender Right

BP-A500-004

\$525

Right fender for Bianchina models from 1957-1960.

\$595



#### Bianchina Rocker Panel Left

BP-A500-005

Left rocker panel for all Bianchina models except the Panoramica

\$148



#### Bianchina Rocker Panel Right

BP-A500-006

Right rocker panel for all Bianchina models except the Panoramica .

\$148



### Bianchina Rear Engine Bridge Holder

BP-A500-007

Rear engine bridge holder for all Bianchina models.

\$450



#### Bianchina Inner Rocker Panel Left BP-A500-009

Inner rocker panel left for Bianchina models. It is not a direct fit, however the panels..

\$214



#### Bianchina Inner Rocker Panel Right BP-A500-010

Inner rocker panel right for bianchina models. It is not a direct fit, however the panels..

\$214



#### Bianchina Panoramica Left Outer...

BP-A500-011

Left outer rocker panel for Bianchina Panoramica models. Part #: BP-A500-011

\$135



#### Bianchina Panoramica Right Outer... BP-A500-012

Right outer rocker panel for Bianchina Panoramica models. Part #: BP-A500-012

\$135



### Bianchina Seat Rail Set

IN-500-110-1

Set of seat rails for Bianchina models. Part #: IN-500-110

\$31



### TERMS AND CONDITIONS

#### PRICES:

We make a real effort to keep our prices as low as possible; however, all prices are subject to change without notice. Most of our parts are imported directly from European manufacturers to give you the best possible prices.

#### STANDARD RETURN POLICY:

- You have 14 calendar days to return an item from the date you received it.
- Please ensure that the item(s) you're returning is repackaged as received

Italian Auto Parts, Inc 2370 John Glenn Dr Atlanta, Ga 30341 United States

Phone: 1-877-9MRFIAT (1-877-967-3428)

Fax: 914-829-9018

#### **SHIPPING CLAIMS:**

We receive excellent service from Fedex and the USPS, although occasionally a mishap occurs. Open any damaged packages in the presence of the carrier, and call us immediately so we can file a claim. If a package arrived damaged all packaging materials must be kept and may be collected and inspected by the carrier when investigating a claim. Missing packages must be reported to Italian Auto Parts, Inc in a timely manner to enable us to file a claim with the carrier. On any orders shipped by truck freight, signing for a shipment constitutes an acknowledgement that the order has been received in good condition; Italian Auto Parts, Inc cannot be held responsible for damage once a truck freight package has been signed for.

This page intentionally left blank

